
RM510C/RM510S Firmware 13.16 Update Available

American Innovations has released the Firmware 13.16 Update for RM510C/RM510S Remote Monitoring Units. The update includes:

- Support for low temperature RM5 Dome operation and faster network acquisition after power outages.
- Addition of network client and registration watchdogs that automatically reset the unit if application code takes too long to execute or the unit takes too long to register.
- A change in file system from LFS to Segger to enhance protection against corruption.
- Out of band reset added to remotely reset a unit if the network client is hanging.
- Improvements from 12.18 firmware update ported to new file system.

The RM510C/RM510S Firmware 13.16 Update can be downloaded from [the Support Software and Files](#) page on the Bullhorn RMU Support Site. Refer to the [Bullhorn Tools Mobile User Guide](#) for instructions on updating a unit.

IMPORTANT: There are separate update files for RM510C and RM510S units. Be sure to download and use the correct file when updating your Bullhorn Remote Monitoring Units.
